

# Smog Check Vehicle Inspection Report (VIR)

## Vehicle Information

Test Date/Time: 10/29/2007 @ 15:01

Model Year: 1984	Make: CHEVROLET	Model: EL CAMINO
License: <del>3B00118</del>	State: CA	VIN: <del>1G00750032207067</del>
Engine Size: 5.0 L	Type: Truck	Transmission: Automatic
GVWR: 4832	Test Weight: 3625	Cylinders: 8
Odometer: 12150	Certification: California	VLT Record #: 40257
Fuel Type: Gasoline	Exhaust: Single	Inspection Reason: High Emitter Profile

### Overall Test Results

**YOUR VEHICLE FAILED AND EXCEEDED THE GROSS POLLUTER LIMITS**

Comprehensive Visual Inspection: **TAMPERED** Functional Check: **FAIL** Emissions Test: **GROSS POLLUTER**

Repairing your vehicle is necessary to help California reduce smog-forming emissions and reach our air quality goals.

### Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test)

<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>
<b>Disconnected</b>	PCV	<b>Disconnected</b>	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	N/A	MIL/Check Engine Light
Pass	EGR Visual	<b>Disconnected</b>	Vacuum Lines to Sensors/ Switches	Pass	Carb./Fuel Injection
N/A	EGR Functional	<b>Fail</b>	Ignition Timing: 4 ATDC	N/A	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	N/A	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls				
N/A	Fuel Evaporative Controls Functional				

### ASM Emission Test Results

Test	RPM	%CO <sub>2</sub>		%O <sub>2</sub>			HC (PPM)			CO (%)			NO (PPM)			Results
		MEAS	MEAS	MAX	GP	MEAS	MAX	GP	MEAS	MAX	GP	MEAS				
15 mph	1261	10.3	6.0	133	321	2497	0.89	2.19	0.13	1090	2057	251	<b>GROSS POLLUTER</b>			
25 mph	1708	10.2	6.1	104	271	2398	1.12	2.42	0.20	1130	2114	148	<b>GROSS POLLUTER</b>			

MAX = Maximum Allowable Emissions

GP = Gross Polluter Limits

MEAS = Amount Measured

Need help with your vehicle's failed smog check? You may be eligible for financial assistance to repair or retire your car. To get an application to see if you and your vehicle qualify, visit the Bureau of Automotive Repair's website at [www.smogcheck.ca.gov](http://www.smogcheck.ca.gov), or call toll-free at 1-800-952-5210. YOUR APPLICATION MUST BE APPROVED BEFORE YOU RECEIVE VEHICLE REPAIR OR RETIREMENT ASSISTANCE.

### Smog Check Inspection Station Information

Kearny Mesa Smog Check  
4191 Convoy Street Suite #A  
(858) 874-8490  
Station Number: TF ~~100009~~

Technician Name/Number: ~~NOVEN THAO NAME 145~~ 145  
Repair Tech Name/Number:  
Software Version/EIS Number: 070 ~~9943~~ 9943

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

\_\_\_\_\_ Date

\_\_\_\_\_ Technician's Signature